

25	X	1
70	$^{\sim}$	

25X1

## SECRET

(IN	35Ø84)	PAGE	TWO
-----	--------	------	-----

INSTALLATION AND BEST POSSIBLE SOLUTION APPEARS TO BE MOUNT INDEX ATTITUDE CASSETTE ON BRACKET HOLDING RECOVERY BEACON BATTERY, RATHER THAN ON PANORAMIC CASSETTE STRUCTURE.

- A. IT SHOULD ALSO BE NOTED THAT THIS AFFECTS INTERCHANGE.

  ABILITY OF INDEX ATTITUDE CAMERA SUBSYSTEM BETWEEN CORONA AND LAN
  YARD PROGRAMS.
  - 5. REQUEST SYSTEMS ENGINEERING BE INFORMED ASAP ON THE FOLLOWING:
- A. CAN INTERCHANGEABILITY BETWEEN PROGRAMS BE MAINTAINED BY FROWIDING FILM TRANSPORT MODULES CAPABLE OF ACCEPTING
  SUPPLY SPOOLS FOR 600 FOOT LENGTH? 140 FOOT LENGTH FOR CORONA?

  B. BOES WISH TO COMMENT ON USE PHILOSOPHY?
- C. DO DIFFERENT OPERATING MODES BETWEEN PROGRAMS OFFER ANY DESIGN PROBLEMS FOR CAMERA SUBSYSTEM CONTROL?
- D. SINCE TIME WORD WILL BE ADDED FOR LANYARD, WHAT IS EFFECT ON CAMERA SUBSTIEM FOR CORONA?

END OF MESSAGE

SECRET